QP Code: 3519

		(3 Hours) [Total Marks:	80
N.B.	(1)	Question no. 1 is compulsory.	
		Attempt any three questions out of remaining five questions.	
		Assume suitable data if necessary.	
		Figures to the right indicate full marks.	
1.	Write	short notes on:-	20
	(a)	Edge dislocation and its significance.	
	(b)	Austempering	
	(c)	Fatigue and significance of cyclic stress	
	(d)	Powder metallurgy	
	(e)	Eutectoid type of alloy phase diagram	
2.	(a)	State and explain various types of ingot defects and suggest remedies for these	10
	(4)	defects.	
7 × E	(b)	Explain toughening mechanism in ceramics and write applications of ceramics.	10
2	(0)	Draw a neat and labelled Fe-FeC diagram ard state its limitations.	10
<ol> <li>4.</li> </ol>		How are composites classified? Explain the rule of mixtures in composites.	10
	(0)	How are composites classified: Explain the full of mixtures in composites.	1000
	(a)	Define Creep. Write about creep testing, data representation and analysis.	10
	(b)		10
	(0)	phase transformation.	
5.	(a)	Draw and label a TTT diagram for 0.8% carbon steel Superimpose various Cooling	10
		curves on it and explain the processes.	
	(b)	Explain the application of lever rule in the context of phase diagrams. Illustrate	10
		your answer with the help of neat sketches.	
6.	White	e short notes on -	20
		Martempering	
	(b)		
	(c)		
	(d)		
	(4)		
	1		