2105 | 8 Q.P.Code: 21933

Total Marks-80

12	Hours)
12	1100121
	/

NB: -	1.Quest	ion No.1	is compulso	ory		
	2. Solve	any thre	e questions	from	remaining	five

3. Assume suitable data wherever necessary

Answer the following questions:

	a)	Draw and explain various surface roughness symbols.	~n
	b)	Compare Mechanical and Pneumatic comparators.	n
	c)	Distinguish between p chart and c chart.	0
		Explain with neat diagram for GO-NOGO plug gauge, Taylor's principle of Gauge Design.	V
	e)	The divisions on main scale of a vernier caliper are 0.5mm apart. The vernier has 100 divisions equal in length to 98 main scale divisions. What is the accuracy of the instrument?	0
02			
V. -	a)	Describe with neat sketch two wire method of measuring the effective diameter of screw threads?	10
	b)	By using optical flat and monochromatic light explain the procedure to determine i) whether the given surface is flat or curved.ii) whether the curved surface is convex or concave.	10
Q.3			
	a)	With the help of graphical representation explain parameters R _a , R _y , R _z and sampling length used in surface texture measurement.	1(
	b) (Define and explain various types of cost of quality with suitable examples.	10
Q.4		Draw the conventional diagram of limits and fits and explain the terms such as Basic Size, Upper deviation, Lower deviation, Fundamental deviation and Zero line.	05
	The state of the s	Why is it necessary to give tolerance on engineering dimension? Give an example of both a unilateral and bilateral tolerance.	05
	(c)	Explain with neat sketch working of Tool Makers Microscope.	10
).5			
	a)	Describe the Parkinson's Gear tester with neat labeled diagram and state its limitations.	10
	b)	Compare X bar chart with R charts. Discuss the circumstances in which either of the two or a combination of these will be used for purpose of control.	10

a) Explain various types of sampling plans which are in practice in 10 industry with their respective acceptance criteria.

b) Explain the Operating Characteristic curve with reference to sampling inspection. Also show various regions in the same with their suitable meaning.