ROD / 22-12-15

QP Code: 5520

(3 Hours)



[Total Marks: 80]

N.B. (1) Question no.1 is compulsory

(2) Answer any 3 questions out of the remaining questions.

(d) Recovery, Recrystallization and Grain Growth.

- (3) Assume suitable data if necessary.
- Q.1. Write Short notes on the following: --(a) Powder metallurgy. (b) Edge and screw dislocations. (c) Classification of cast irons. (d) Rules of mixtures in composites. Draw iron- iron carbide phase diagram and explain various phase transformation reactions from different regions of the diagram. State and explain various types of ingot defects and suggest remedies for these defects. Write short note on how composites are classified on the basis of matrix Q.3. (a) material. Give example of each type with applications. (b) Explain in brief at least two types of stainless steel in terms of properties and applications. Compare in the form of a table, the properties of engineering ceramics with 10 Q.4. (a) the properties of metallic alloys, giving relevant examples of applications. Write short note on creep testing, data representation and analysis. 10 Q.5. (a) Write about the unique features of Nano-structured materials. (b) Define hardenability? How is hardenability determined? Explain Jomny end 10 quench hardenability test. 5 Distinguish between Cyaniding and Carbonitriding. 20 Write short notes on :-Eutectoid type of alloy phase diagram. (b) Fatigue failure. Alloys of Aluminium.