SE Electrical-IV-CBGs EM-I Q.P. 25.5.16

Q.P. Code: 543802

(3 Hours)

[Total Marks: 80

Question No.1 is compulsory.

- Attempt any THREE from the remaining questions.
- Figures to the right indicate full marks.
- Attempt any Four questions:
 - What are the advantages of auto transformer over two winding transformer.
 - How the losses can be minimise in case of single phase transformer?
 - What is Electromechanical Energy Conversion?
 - Which speed control methods are used to get the speed above normal and below normal in case of DC Motor?
 - List the advantages of Hopkinson's test.
- 2. (a) Derive the expression for torque developed in singly excited system. 10
 - (b) 5 kVA, 200 / 400 V, 50 Hz single phase transformer gave following test 10 result.

O.C. Test: 200 V, 0.9 A, 60 W (L. V. Side)

S.C. Test: 10 V, 6 A, 22 W (H. V. Side)

Calculate:

- Efficiency and voltage regulative at full load 0.8.
- Efficiency at 25% load at unity p.f. (11)
- Explain the different electrical braking methods for separately excited DC Motor.
 - Two single phase transformer with equal voltage ratio having impedance 10 of (0.819 + j 2.503) Ω and (0.8 + j 2.31) Ω with respect to secondary. If they operated in parallel how they will share the load of 3000 kw at p.f. 0.9 lagging

TURN OVER

25.5.16

Q.P. Code: 543802

2

| 4. | (a) | | 1 |
|----|------------|---|----|
| | (b) | A conductor of 4 m length moves under a magnetic field of flux density | 1 |
| | | of 1.3 wb/m2 with velocity of 1.3 m/s calculate the magnitude of induced e.m.f. if conductor moves | |
| | | (i) An angle of 50° to direction of field and | |
| | | (ii) At 90° to axis of field. | |
| 5. | (a) | Explain commutation in DC machine also explain the various methods of the improvement. | 10 |
| | (b) | Explain the characteristics of DC series and shunt motors, | 10 |
| | (a) (b) | Draw and explain four point starter. Derive the expression for colonlation 1 | 10 |
| | (-) | Derive the expression for calculation demagnetising ampere turns per pole and cross magnetisly ampere turns per pole. | 10 |

2